

情况说明

致上海睿齐实业有限公司

贵单位所购产品 T_70114955127- Lot# 202006150401 比色皿-产品表面有 Y 型痕的问题，经与供应商确认后，得出以下结论，望知悉：

Jpg. A : It is the illuminating surface and we must check if it is scratched as this side is working side

Jpg. B :This surface is what you find have scratch like "Y". The scratches(the injection combine line) cannot avoid during the injection process. And due to this is not on the working surface, and it will not affect the application.

And pls noted:

The reason for the scratch like "Y" :It is a weld mark happen during injection moulding. So the location of "Y " scratch is similar . If it is a scratch , it will be a straight line not a "Y " type. The "Y" scratch can not be removed and will not affect your test result.

造成类似“Y”痕迹的原因是注塑过程中出现的焊接痕。因此，“Y”痕迹的位置是相似的。如果是划痕，它将是一条直线，而不是“Y”型。“Y”划痕不能去除，也不会影响测试结果。